



7511

Unit 12, Tallon Road, Hutton Industrial Estate, Brentwood, CM13 1TF  
Tel.: 01277 220633 Email: Chris@bauerc.co.uk

## Asbestos Management Survey Report

London Biggin Hill Airport  
Main Road  
Biggin Hill  
TN16 3BH

On behalf of  
Biggin Hill Airport Limited

Report Reference: A-29662



## ASBESTOS REGISTER

Building / Floor	Area / Room	Accessi bility	Material	Extent	Condition	Surface Treatment	Sample Number	Asbestos Type	Material Score	Recommended Action	Next Inspection
Pump House / Ground Floor	002 - Room 2	Difficult	Flashguards - Woven Product	<1 lin m	Good Condition	Unsealed cement / Enclosed lagging or spray / Encapsulated board	P001	Chrysotile	4 - Very Low	Manage	20-07-2021

Building / Floor	Area / Room	Accessibility	Material	Extent	Condition	Surface Treatment	Sample Number	Asbestos Type	Material Score	Recommended Action	Next inspection
Localiser Hut / Ground Floor	002 - Room 1	Difficult	Flashguards - Woven Product	<1 lin m	Good Condition	Unsealed cement / Enclosed lagging or spray / Encapsulated board	P003	Chrysotile	4 - Very Low	Manage	20-01-2021

Building / Floor	Area / Room	Accessibility	Material	Extent	Condition	Surface Treatment	Sample Number	Asbestos Type	Material Score	Recommended Action	Next inspection
Glide Slope Hut / External	001 - External	Medium	Beneath timber panels - Bituminous Product	9 m <sup>2</sup>	Good Condition	Composite, reinforced or bonded	S002	Crocidolite	4 - Very Low	Manage	20-01-2021
Glide Slope Hut / Ground Floor	002 - Room 1	Easy	Floor - Floor tiles & Adhesive	8 m <sup>2</sup>	Good Condition	Composite, reinforced or bonded	S003	Crocidolite	4 - Very Low	Manage	20-01-2021
Glide Slope Hut / Ground Floor	002 - Room 1	Difficult	Flashguards - Woven Product	<1 lin m	Good Condition	Unsealed cement / Enclosed lagging or spray / Encapsulated board	P004	Chrysotile	4 - Very Low	Manage	20-07-2021

Building / Floor	Area / Room	Accessibility	Material	Extent	Condition	Surface Treatment	Sample Number	Asbestos Type	Material Score	Recommended Action	Next inspection
Milking Lane Farm / External	001 - External	Difficult	Corrugated roof sheets - Profiled cement sheeting	300 m <sup>2</sup>	High Damage	Unsealed cement / Enclosed lagging or spray / Encapsulated board	S001	Chrysotile	6 - Low	To be removed by an Asbestos Contractor	N/A
Milking Lane Farm / External	001 - External	Easy	Walls - Profiled cement sheeting	200 m <sup>2</sup>	High Damage	Unsealed cement / Enclosed lagging or spray / Encapsulated board	S002	Chrysotile	6 - Low	To be removed by an Asbestos Contractor	N/A
Milking Lane Farm / External	001 - External	Easy	Debris to floor - Cement Product	600 m <sup>2</sup>	High Damage	Unsealed cement / Enclosed lagging or spray / Encapsulated board	S003	Chrysotile	6 - Low	To be removed by an Asbestos Contractor	N/A
Milking Lane Farm / External	001 - External	Easy	Debris - Cement Product	20 m <sup>2</sup>	High Damage	Unsealed cement / Enclosed lagging or spray / Encapsulated board	S004	Chrysotile	6 - Low	To be removed by an Asbestos Contractor	N/A
Milking Lane Farm / External	001 - External	Difficult	Flashguards - Woven Product	1 m <sup>2</sup>	Good Condition	Unsealed cement / Enclosed lagging or spray / Encapsulated board	P005	Chrysotile	4 - Very Low	To be removed by an Asbestos Contractor	N/A

Building / Floor	Area / Room	Accessibility	Material	Extent	Condition	Surface Treatment	Sample Number	Asbestos Type	Material Score	Recommended Action	Next inspection
Main Building, First Floor	External Roof/windows	Difficult	Mastic	40lm	High Damage	Bitumen Products	S15	Chrysotile	5	Manage	20-01-2021
Main Building, First Floor	External Roof/Rainwater Down Pipes	Difficult	Asbestos cement	16lm	Low Damage	Cement sheets	S16	Chrysotile	4	Manage	20-07-2021
Main Building Ground floor	Gate 2/ Windows	Easy	Mastic	18lm	Good Condition	Bitumen Product	S27	Chrysotile	2	Manage	20-01-2021
Main Building Ground Floor	Gangway/windows	Easy	Mastic	12lm	Good Condition	Bitumen Product	S43	Chrysotile	2	Manage	20-01-2021
Main Building Ground floor	External/Rainwater pipe	Easy	Cement	6lm	High damage	Cement sheets	S50	Chrysotile	6	Removed -15-08-2020	N/A
Main Building second floor	Control Tower/electric box	Difficult	Electric box/ropes and woven textiles	1lm	Low Damage	Sealed ropes/textiles	V03	Chrysotile	5	Manage	20-01-2021
Main Building ground floor	Mains Room	Difficult	Flashguards	1lm	Low Damage	Unsealed ropes/textiles	V28	Chrysotile	6	Manage	20-07-2021
Main Building Ground Floor	CCR Room	Difficult	Flashguards	1lm	Low Damage	Unsealed ropes/textiles	V29	Chrysotile	6	Manage	20-07-2021
Main Building Ground Floor	External/rainwater pipe debris	Easy	Rainwater Pipe Debris	1lm	High	Asbestos cement sheets	V51	Chrysotile	6	Removed – 15-08-2020	N/A

Building / Floor	Area / Room	Accessibility	Material	Extent	Condition	Surface Treatment	Sample Number	Asbestos Type	Material Score	Recommended Action	Next inspection
Main Building, Ground Floor	Dispersal Hut	Difficult	Flash Guards	1lm	Low Damage	Unsealed rope/textiles	S01	Chrysotile	6	Removed – 15-08-2020	N/A
Main Building, Ground floor	Dispersal Hut	Easy	Flash Guards	1m2	High Damage	Unsealed rope/textiles	S03	Chrysotile	8	Removed – 15-08-2020	N/A
Main Building Ground floor	Dispersal Hut	Easy	Flash Guards	1m2	High Damage	Unsealed rope/textiles	S04	Chrysotile	8	Removed - 15-08-2020	N/A
Main Building Ground Floor	Dispersal Hut	Difficult	Flash Guards	1lm	Low Damage	Unsealed rope/textiles	S07	Chrysotile	6	Removed - 15-08-2020	N/A